

Product Safety Recall

Urgent update - 19 December 2023

BEEFEATER REFRIGERATORS (BEVERAGE CHILLER) BS28130 & BS28200 SINGLE & DOUBLE DOOR



DOUBLE DOOR REFRIGERATOR UPDATE (model number BS28200)

Consumers who have had their double door refrigerator repaired under this recall should **turn the refrigerator off immediately and do not use.**

Consumers with affected refrigerators should contact Electrolux for a refund or replacement.

This update is for all consumers who have had their affected double door refrigerator repaired, including the double door refrigerators repaired before 6 March 2023. Repairs of the refrigerator under this recall were stopped on 16 November 2023.

Identifying features:

Refrigerator (beverage chiller) - single and double door versions designed for outdoor use.

- Model Numbers: Double Door BS28200 & Single Door BS28130.
- Serial Number ranges: 72900000 to 95299999, and 00100000 to 04599999 only.
- Certificate number SGS/180357, OTR200146, OTR200271.
- Sold approximately July 2017 – November 2021 | Manufactured July 2017 – November 2020

Defect: Water can penetrate the sealed electrical control board located on the rear of the refrigerator.

Hazard: The refrigerator may cause a fire, posing a risk of injuries and damage to property. The defect has caused fires in double door units, including repaired units, resulting in property damage and injuries.

What to do: Turn the refrigerator off immediately and unplug it from the electricity supply. Contact Electrolux to arrange for the choice of a refund or replacement product.

Contact details: Contact Electrolux Home Products toll-free number 1800 001 218 between 8am and 7pm AEST Monday - Friday or email productrecall@electrolux.com or visit www.beefeaterbbq.com/en-au/support-page/product-recall/

**See productsafety.gov.au for
Australian product recall information**